




# Gen4 - Creating Guidance Lines

1 Select the "Menu" button in the bottom right of the screen




2 Select "Applications" on the left side of the screen




3 Select "AutoTrac Guidance"




4 Notice the AutoTrac Master cannot be turned on if there is no guidance line selected



**5** Select "Set Track" on the right side of the screen




6 Select "New Track"



7 In the "Straight Track" section, select "A + B Method"




8 Name the Track




Select "OK"

| Mew Guidance Track | Method:
| A + B |
| Modified:
| 12-29-2022 03:08 PM |
South 40	We Cancel	Calculation		
John Deere	Cancel	Cancel		
Cancel	Cancel	Cancel	Cancel	
Cancel	Cancel	Cancel	Cancel	
Cancel	Cancel	Cancel	Cancel	
Cancel	Cancel	Cancel	Cancel	
Cancel	Cancel	Cancel	Cancel	
Cancel	Cancel	Cancel	Cancel	Cancel
Cancel				
Canc				

**10** Select "Set A" and move the machine forward



Select "Set B." Once hitting this, system will snap a line directly between Point A and Point B.



Once a line has been established, the AutoTrac button can be pressed to enable AutoTrac




Gen4 AutoTrac Troubleshooting

#### 13 Click Menu




## 14 Click System




## Click the Diagnostics Center



### Click Guidance - AutoTrac



17 For additional information Click the Help Icon



**18** For additional Help Read the AutoTrac Health.

